

Hamilton Conservation Authority (HCA)

Project Title	Sector	Location	Client
Coastal Analysis and Seawall Design for 56 Seabreeze Crescent, Stoney Creek	CP	ON, Canada	Property Owner
Revetment Design & Coastal Engineering Analysis at 1097 North Service Rd	CP	ON, Canada	Property Owner
Flood Hazard Assessment and Coastal Analysis for 16 and 18 Lakeside Drive, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design at 658 North Shore Boulevard East, Burlington	CP	ON, Canada	Property Owner
Coastal Engineering Analysis, Revetment Repairing, and Design for 45 Windemere Road, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design for 645 Grays Road	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design 24 Trillium Avenue, Stone Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design for 531 Winona Road, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design for 29 Lochside Drive, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design for 24 Trillium Avenue, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design at 1061-1065 North Service Road	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design at 15 Lakegate Drive, Stoney Creek	CP	ON, Canada	Property Owner
Hazard Limit Delineation and Revetment Design for 2 Lakeside Drive, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis, Dynamic Beach and Hazard Limit Delineation at 7 Woodland Avenue, Hamilton	CP	ON, Canada	Property Owner
Coastal Analysis, Revetment Repairing and Design for 43 Windemere Road, Stoney Creek	CP	ON, Canada	Property Owner
Seawall Repair & Hazard Limit Delineation at 12 Lakeside Drive, Stoney Creek	CP	ON, Canada	Property Owner
Groin Structure Repairment at 7 Lakegate Drive, Stoney Creek	CP	ON, Canada	Property Owner
Seawall Repair and Design for 34 Lakeshore Drive, Stoney Creek	CP	ON, Canada	Property Owner

Coastal Analysis and Seawall Design at 1069-1073 North Service Road, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Engineering Analysis, Seawall Repair and Design for 47-49-51 Windemere Road, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Engineering Analysis, Repair and of Existing Groyne and Seawall for 23 Lakegate Drive, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Engineering Analysis and Revetment Design for 32 Trillium Avenue, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Engineering Analysis, Hazard Limit Delineation, and Groin Design for 1031 North Service Road, Stoney Creek	CP	ON, Canada	Property Owner
Seawall and Toe Protection for Property at 63 Lake View Drive, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Hazard Limit Delineation for 49 Lakeview Drive, Stoney Creek, Hamilton	CP	ON, Canada	Property Owner
Coastal Analysis and Hazard Limit Delineation for 93 Creanona Boulevard, Stoney Creek, Hamilton	CP	ON, Canada	Property Owner
Coastal Hazard Limit Delineation and Sewall design for 6 Trillium Avenue, Stoney Creek	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall Design for 56, 60, 64 & 68 Aquamarine Drive, Hamilton	CP	ON, Canada	Property Owner
Coastal Analysis and Revetment Design for the Property at 34 & 36 Seabreeze Crescent, Hamilton	CP	ON, Canada	Property Owner
Coastal Engineering Analysis and Hazard Limit Delineation for 10 first private Road.	CP	ON, Canada	Property Owner
Coastal Engineering Analysis, Hazard Limit Delineation and Seawall Design for 10 Lakeside Drive, Stoney Creek	CP	ON, Canada	Property Owner