

Conservation Halton (CH)

Project Title	Sector	Location	Client
Geomorphic Assessment and Meander Belt Analysis of Sheldon Creek, 2124 Orchard Road (Block 40) - Burlington	FG	ON, Canada	The Krpan Group of Companies
Coastal Engineering Analysis, Revetment Repairing and Design for 1306 Lakeshore Road West, Oakville	CP	ON, Canada	Property Owner
Coastal Engineering Analysis and Hazard Limit Delineation at 2136 Old Lakeshore, Burlington	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall/Revetment Design for 260-270-274 North Shore Boulevard East, Burlington	CP	ON, Canada	Property Owner
Coastal Engineering Analysis and Shoreline Protection Structure Design for 5370-5380 Lakeshore Rd, Burlington	CP	ON, Canada	Property Owner
Armour Stone Revetment Design at 682-688 Northshore Blv, Burlington	CP	ON, Canada	Property Owner
Consulting Design Services for Shoreline Rehabilitation and Protection at Green Street and Port Nelson Park	CP	ON, Canada	City of Burlington
Coastal Engineering Analysis and Seawall Design for 584 North Shore Boulevard East	CP	ON, Canada	Property Owner
Seawall Repairment for Property at 160 Nicholson Court, Burlington	CP	ON, Canada	Property Owner
Flooding and Erosion Hazard Analysis for 3132 Lakeshore Road, Burlington	CP	ON, Canada	Property Owner
Coastal Analysis and Seawall with Steel Sheet Pile Design for 3172 Lakeshore Road, Burlington	CP	ON, Canada	Property Owner
Coastal Analysis and Hazard Limit Delineation for 1538 Bayview Road, Oakville	CP	ON, Canada	Property Owner
Coastal Engineering Analysis and Seawall Design for 232 Green Street, Burlington	CP	ON, Canada	Property Owner
Engineering Analysis to Assess Restoration Plan for 8329 Esquesing Line, Milton	HH	ON, Canada	WFS Transport
Coastal Analysis and Boat Ramp Design for 590 North Shore Boulevard East, Burlington	CP	ON, Canada	Property Owner
Hydrologic, Hydrodynamic & Flood Hazard Analysis of Fourteen Mile Creek for 514 Stafford Drive, Oakville	HH	ON, Canada	Property Owner