Nottawasaga Valley Conservation Authority (NVCA)

Project Title	Sector	Location	Client
Wasaga Beach Floodplain Mapping and Watershed Hydrology	НН	ON, Canada	Nottawasaga Valley Conservation Authority (NVCA)
Tottenham Dam Break and Flooding Hazard Analysis	HH	ON, Canada	Township of New Tecumseth
Floodplain Mapping of Innisfil Creek Golf Club	НН	ON, Canada	Innisfil Creek Golf Club
Fluvial Geomorphic Assessment and Vegetated Buttress Design for Nottawasaga River at 37 Cottage Road, Mono	FG	ON, Canada	Property Owner
Fluvial Geomorphic and Erosion Hazard Assessment of Innisfil Creek Tributary at 239 Reive Boulevard, Cookstown	FG	ON, Canada	Innisfil Creek Golf Club
Stormwater Management Facility sediment survey for Sleeping Lion Development	SCD	ON, Canada	Town of Innisfil
Stormwater Management Facility sediment survey for Innisfil Executive Estates	SCD	ON, Canada	Town of Innisfil
Sediment Survey at Carson Creek and Banks Creek Outlets	SCD	ON, Canada	Town of Innisfil